

THE ALDE & ORE ASSOCIATION

Registered Charity No. 1154583




ALDE AND ORE ESTUARY ASSESSORS REPORT

NAME:	John Grayburn Roger Baxter	DATE OF INSPECTION:	1st May 2017
LOCATION:	Flood Cell 3		
AREA OF ASSESSMENT:	Chillesford Marshes		March Equinox

SUMMARY

River Wall/Armour	Saltings	High Tide Debris Line
Good condition	In good order	Low

River bank surveyed:



OVERVIEW

- Good saltings rising to hill/cliff behind.
- Low debris line. Wall good with a perfect back slope.
- No change in armour. Some break up of revetments, but not a concern.
- Strong vegetation on top of wall.
- At the point, old revetment blocks giving protection with a build up of silt within.