

THE ALDE & ORE ASSOCIATION

Registered Charity No. 1154583



ALDE AND ORE ESTUARY ASSESSORS REPORT

NAME: Roger Baxter John Grayburn Tim Dudgeon Alison Andrews Diana Paterson	DATE OF INSPECTION: 5th May 2017
LOCATION: Flood Cell 4-4	
AREA OF ASSESSMENT: Chapmans Creek to Pump House	March Equinox

SUMMARY

River Wall/Armour	Saltings	High Tide Debris Line
Mainly good	Non-existent area north of Pump House	Not significant

River bank surveyed



OVERVIEW

- First section of wall needs cutting.
- Gorse bushes growing on top (see Photograph 1).
- 300m of poor saltings north of Pump House behind electric fencing (see Photographs 2 & 3).
- Attenuation system requires upgrading. Partial collapse of mesh preventing accretion.
- Walls generally robust, top well cropped where sheep have grazed.
- Debris - where there is any - is well below wall and top (see Photograph 4)
- Saltings with old defence posts (see Photograph 5)



Photograph 1



Photograph 2



Photograph 3



Photograph 4



Photograph 5