

# THE ALDE & ORE ASSOCIATION

Registered Charity No. 1064789




## ALDE AND ORE ESTUARY ASSESSORS REPORT

<b>NAME:</b> Roger Baxter	<b>DATE OF INSPECTION:</b> April 2017 [Photos June 2017]
<b>LOCATION:</b> Flood Cell 9	
<b>AREA OF ASSESSMENT:</b> Brick Dock to Hazlewood Marsh	March Equinox

### SUMMARY

River Wall/Armour	Saltings	High Tide Debris Line
Wall in good condition	Erosion below vegetation	No Problems

River bank surveyed:



## OVERVIEW

River wall from Brick Dock to Roundhill is in good repair, with thick vegetation. However, Roundhill to the breach on Hazelwood Marsh has several areas where revetment is breaking up at the water line. Above the armour the wall is robust with good vegetation (Photograph 3).

Salting depth varies, as the beach area (Photograph 1) is suffering from vegetation root washout (Photograph 2). However, the area behind is rising ground. Saltings are deeper towards Roundhill and in good condition (Photograph 4).

No evidence of any overtopping.



Photograph 1



Photograph 2





Photograph 3



Photograph 4