THE ALDE & ORE ASSOCIATION

Registered Charity No. 1154583




ALDE AND ORE ESTUARY ASSESSORS REPORT

NAMES:	John Grayburn Alison Andrews Nick Robinson Roger Baxter	DATE OF INSPECTION: 24 April 2018
LOCATION:		AREA OF ASSESSMENT:
	Flood Cell 3	Chillesford Marshes

SUMMARY

River Wall/Armour	Saltings	High Tide Debris Line
Mainly good with some loose armour blocks	Good	Low 5 feet below wall top

River Bank Surveyed:



OVERVIEW & PHOTOS

Walls well covered in vegetation with no risk of erosion in the event of over-topping.

A few armour blocks have become loose, but not causing concern.

Where armour has been replaced in the past, the old material has been left to provide additional protection.









