

THE ALDE & ORE ASSOCIATION

Registered Charity No. 1154583



ALDE AND ORE ESTUARY ASSESSORS REPORT

NAMES:	Simon Reid Roger Baxter	DATE OF INSPECTION:	May 2018
LOCATION:	Flood Cell 4.4	AREA OF ASSESSMENT:	Pump House to Chapmans Creek

SUMMARY

River Wall/Armour	Saltings	High Tide Debris Line
Good vegetation	Westrow Reach poor	Low, not a problem

River Bank Surveyed:



OVERVIEW & PHOTOS

River wall well covered in vegetation, in better condition where sheep have grazed (photo 3)
Back slope shallow, some areas of river slope steep, but not a problem.





Where saltings are deep there are some lagoons. Saltings on Westrow Reach (where some attenuation system is in place) erosion continues.



