THE ALDE & ORE ASSOCIATION

Registered Charity No. 1154583




ALDE AND ORE ESTUARY ASSESSORS REPORT

NAMES:	Peter Donaldson Rufus Gilday Richard Kihl	DATE OF INSPECTION: 20 April.2018
LOCATION:	Flood Cell 8	AREA OF ASSESSMENT: Ham Creek

SUMMARY

River Wall/Armour	Saltings	High Tide Debris Line
Good condition	Good and deep in places	Low

River Bank Surveyed:



OVERVIEW & PHOTOS

Minor loss of armour, exposing underlying material (see photo 1). Needs to be watched.

Wall at the creek holding well with good vegetation – at 2.1m it is low, but it is planned to raise the area in the future.

Sandstone cliff - no appreciable erosion since the last report.



