

THE ALDE & ORE ASSOCIATION

Registered Charity No. 1154583



ALDE AND ORE ESTUARY ASSESSORS REPORT

NAME: Roger Baxter	DATE OF INSPECTION: June 2018
LOCATION: Flood Cell 9	AREA OF ASSESSMENT: Brick Dock

SUMMARY

River Wall/Armour	Saltings	High Tide Debris Line
Wall behind the beach is sound with thick vegetation. Armour breaking up at the upstream end of Round House land. Getting worse.	Vegetation in sand suffering from tidal erosion on the beach. Further upstream, saltings are deep but covered during high tide.	Low level

River Bank Surveyed:





