

THE ALDE & ORE ASSOCIATION

Registered Charity No. 1154583



ALDE AND ORE ESTUARY ASSESSORS REPORT

NAME: Roger Baxter Michael Hazeldene Jane Salter	DATE OF INSPECTION: 27 May 2019
LOCATION: Flood Cell 2	AREA OF ASSESSMENT: Butley Mills

SUMMARY

River Wall/Armour	Saltings	High Tide Debris Line
Very Good	Deep thick reeds	No evidence

River Bank Surveyed:



OVERVIEW & PHOTOS

A solid wall separates the road from the saltings. A mill stream on one side flows underneath and drains through two controllable sluices into the marsh and onto the river.

The wall is in good condition with good vegetation and thick grass. This is cut annually in September.

The saltings/marsh is deep and flat down to the Butley River channel.





