

THE ALDE & ORE ASSOCIATION

Registered Charity No. 1154583



ALDE AND ORE ESTUARY ASSESSORS REPORT

NAMES: Frances Barnwell Susie Bridges	DATE OF INSPECTION: 6 May 2019
LOCATION: Flood Cell 4.2	AREA OF ASSESSMENT: Chantry Marshes to Orford Quay

SUMMARY

River Wall/Armour	Saltings	High Tide Debris Line
There was no discernible change save for continuing deterioration of the top surface referred to below.	Overhangs from last year were no longer present on Short Gull indicating continuing loss.	Not clear on the day of our survey.

River Bank Surveyed:



OVERVIEW & PHOTOS

As with all FC4.2 reports, the key concern is the continuing deterioration of the top surface. In the dry weather preceding the survey, cracks had opened up in the exposed areas of mud as shown in the photographs below.

The netting has lifted creating a significant trip risk as shown on the photograph. It is not clear who is responsible for repair of this section (between the sewage outlet and stile).

Photo 1 – Cracking in side of wall by sewage outlet



Photo 2 – Erosion under netting



Photo 3 – Tripping Hazard



Photo 4 – Cracking on path
[a feature through the length of the survey]



Photo 5 – Cracking on path

