

THE ALDE & ORE ASSOCIATION

Registered Charity No. 1154583



ALDE AND ORE ESTUARY ASSESSORS REPORT

NAME: Simon Reid Sue Ingham	DATE OF INSPECTION: 5 May 2019
LOCATION: Flood Cell 4.3	AREA OF ASSESSMENT: Pump House to Orford Quay

SUMMARY

River Wall/Armour	Saltings	High Tide Debris Line
Mostly good with well established grass. Fine back slopes	Variable. Some areas shallow, others with lagooning.	Low – no problem.

River Bank Surveyed:



OVERVIEW & PHOTOS

Mostly problem free, with minor exceptions (as below). The wall is a public footpath with regular use.

Hedges still growing [435 535]



Vertical hole less noticeable [450 525]



Dip in wall getting bigger [437 500]

