

THE ALDE & ORE ASSOCIATION

Registered Charity No. 1154583



ALDE AND ORE ESTUARY ASSESSORS REPORT

NAMES:	Roger Baxter Jonathan Evans Richard Kihl Jeremy Nice	DATE OF INSPECTION:	14 May 2019
LOCATION:	Flood Cell 8	AREA OF ASSESSMENT:	Ham Creek

SUMMARY

River Wall/Armour	Saltings	High Tide Debris Line
Good condition – to be raised	Wide with good vegetation	Low

River Bank Surveyed:



OVERVIEW & PHOTOS

Upstream stretch has wide saltings with a beach and sand cliff behind. Debris here is at a low level with no risk of flooding.



At Ham Creek the wall down to the sluice has been repaired with flint stone which is holding well.



There are plans to raise the wall to 3.5m. However, the wall is in good shape, apart from the top slopes to the back. There is good vegetation and the wall profile is fine.



The old oak tree adds to the beauty of this part of the estuary.

