

# THE ALDE & ORE ASSOCIATION

Registered Charity No. 1154583




## ALDE AND ORE ESTUARY ASSESSORS REPORT

<b>NAME:</b> Roger Baxter	<b>DATE OF INSPECTION:</b> April 2019
<b>LOCATION:</b> Flood Cell 9	<b>AREA OF ASSESSMENT:</b> Brick Dock

### SUMMARY

River Wall/Armour	Saltings	High Tide Debris Line
Beach with thick vegetation behind.. Broke armour upstream has not changed.	Lower vegetation in sand suffering from tidal erosion on sand. Further upstream, saltings are deep but covered during high tide.	Low level

### River Bank Surveyed:



## OVERVIEW:

There was little change this year over 2018. The beach rises into a well vegetated wall, behind which is a meadow with no risk of flooding.

The saltings are wide and are submerged at high tide. The river wall is robust with rising ground behind.

(Library photos below illustrate conditions).



