THE ALDE & ORE ASSOCIATION

Registered Charity No. 1154583




ALDE AND ORE ESTUARY ASSESSORS REPORT

NAME[S]: R Baxter	DATE OF INSPECTION: September 2020	
FLOOD CELL:	AREA OF ASSESSMENT:	
FC2	Butley Mills	

SUMMARY

River Wall/Armour	Saltings	High Tide Debris Line
Very good	Reed beds	Not evident

River Bank Surveyed:



OVERVIEW & PHOTOS

The river wall separates the lane from the estuary.

The wall is substantial, with good vegetation cover. Path little used and no evidence of horse damage, as in previous years.

Reed beds are dense and cover the saltings down to the Butley river channel. Two sluices provide adequate drainage from the mill ponds.



Photo 1



Photo 2