

THE ALDE & ORE ASSOCIATION

Registered Charity No. 1154583




ALDE AND ORE ESTUARY ASSESSORS REPORT

NAME[S]: A McDonald +	DATE OF INSPECTION:
FLOOD CELL: FC4.1	AREA OF ASSESSMENT: Gedgrave & Sudbourne Marshes

SUMMARY

River Wall/Armour	Saltings	High Tide Debris Line
No degeneration or obvious changes since last year, with the exception of repairs at Gedgrave Pumping Station. Generally in good condition and very well grassed on inner slopes.	Good condition from Inset Point to Tide gauge, but further widening of channels and new openings from Butley Ferry to Boyton Dock.	Marked absence of debris compared with previous years.

River Bank Surveyed:



OVERVIEW & PHOTOS [with grid reference]

Inner walls and pathway – all well grassed and no evidence of damage or change since last year; pathways occasionally showing deep cracking following a very dry month, but not slippage or decay.



By Pinneys TM397486



Opposite Ferry TM396 485



Above Ferry TM394 483



Boyton Dock TM395 474



Above B Dock TM399 474



Towards Gedgrave PS TM406 472



Path at Gedgrave PS TM407 472



Twds Gedgrave PS TM411 475



Towards Tide Gauge TM412 479

Saltings: once more, widening channels and undercutting at Butley Ferry, better elsewhere, though slight widening of inner channel along Long Gull.



At Butley Ferry, TM 395 484



Above Ferry TM 394 482



Channel widening TM394 479



Channel above B Dock TM397 474



Better! Long Gull TM400 474



Some channel formation, undercutting: TM407 471

Outer Walls – generally good condition and no evidence of any change or deterioration



Armour at Gedgrave PS TM411 475



Shore twds Tide Gauge TM412 477



Further twd TG TM 412 478