

THE ALDE & ORE ASSOCIATION

Registered Charity No. 1154583




ALDE AND ORE ESTUARY ASSESSORS REPORT

NAMES: Jonathan Evans Richard Kihl Roger Baxter	DATE OF INSPECTION: September 2021
FLOOD CELL: FC7	AREA OF ASSESSMENT Snape Bridge to Blackheath

SUMMARY

River Wall/Armour	Saltings	High Tide Debris Line
Good Condition. Wide Top (well used). Banks with good vegetation.	Mostly at the bottom of the Warren. Deep, flat. Reed Beds to the East between wall and tidal channel.	Low, little evidence.

Area Surveyed:



OVERVIEW & PHOTOS



Wall with well used path and good vegetation each side



Inner slope (N) on to marsh land and pasture



River wall looking towards Snape Warren. Reed beds in abundance.



River channel showing mud flats at low tide



Marsh and saltings at Snape Warren



Beautiful Scenery looking towards the Maltings



Iken Church



Snape Bridge with barge Cygnet on the quay