

THE ALDE & ORE ASSOCIATION

Registered Charity No. 1154583




ALDE AND ORE ESTUARY ASSESSORS REPORT

NAMES: Jonathan Evans Roger Baxter	DATE OF INSPECTION: Spring and Summer 2021
FLOOD CELL: FC9	AREA OF ASSESSMENT: Brick Dock to Hazlewood Marsh

SUMMARY

River Wall/Armour	Saltings	High Tide Debris Line
Sandy beach at the dock. Wall has rising ground behind. Some broken armour at base of wall beyond Roundhill. Breaches at Colliers Hole becoming wide with tidal flow.	Saltings good further upstream from beach with concrete wall behind.	Low, little evidence.

Area Surveyed:



OVERVIEW & PHOTOS



River Wall looking towards Brick Dock



Beach and Jetty



Debris with wall behind, Good vegetation. Rising ground beyond.



Broken armour



Broken armour at base of wall



Wall separating river from marsh looking upstream towards Colliers Hole.
Yarn Hill in the distance.