

# THE ALDE & ORE ASSOCIATION

Registered Charity No. 1154583



(Two swans at TM 400 478)


## ALDE AND ORE ESTUARY ASSESSORS REPORT

<b>NAME[S]:</b> A McDonald Sue Skeen	<b>DATE OF INSPECTION:</b> 27/10/2021
<b>FLOOD CELL:</b> FC4.1	<b>AREA OF ASSESSMENT:</b> Gedgrave & Sudbourne Marshes

### SUMMARY

River Wall/Armour	Saltings	High Tide Debris Line
No obvious changes since last year, repairs at Gedgrave Pumping Station now well grassed over. Generally in good condition and very well grassed on inner slopes. Some cracked patches on path towards Tidal gauge.	Good condition from Inset Point to Tide gauge, although some channel formation evident; but yet more widening of channels and new openings from Butley Ferry to Boyton Dock.	Once again a marked absence of debris compared with previous years.

### River Bank Surveyed:



## OVERVIEW & PHOTOS [with grid reference]

**Inner walls and pathway** – all well grassed and no evidence of damage or change since last year; pathways past the pumping station showing some cracking despite recent rain and the lateness of the survey, but no slippage.



By Pinneys TM397486



Opposite Ferry TM396 485



Above Ferry TM394 483



Boyton Dock TM395 474



Above B Dock TM399 474



Towards Gedgrave PS TM406 472



Path at Gedgrave PS TM407 472



Twds Gedgrave PS TM411 475



Towards Tide Gauge TM412 479

**Saltings:** Further widening of channels and more undercutting around the Ferry; not so bad further downstream though inner channel along the LG still widening, some new undercutting.



At Butley Ferry TM 395 484



Above Ferry TM 3944 482



Channel Widening TM 394 479



Channel above B Dock TM397 474 Long Gull TM400 474



New undercutting and widening TM 407 471



**Outer Walls** – generally good condition and no evidence of any change or deterioration



Armour at Gedgrave PS TM411 475



Shore twds Tide Gauge TM412 477



Further twd TG TM 412 478