

# THE ALDE & ORE ASSOCIATION

Registered Charity No. 1154583




## ALDE AND ORE ESTUARY ASSESSORS REPORT

<b>NAME:</b> Frances Barnwell Christopher Gill Jane Maxim Richard	<b>DATE OF INSPECTION:</b> <p style="text-align: center;">14.04.2021</p>
<b>FLOOD CELL:</b> <p style="text-align: center;">4.2</p>	<b>AREA OF ASSESSMENT:</b> <p style="text-align: center;">Chantry Marshes to Orford Quay          [Orford Sailing Club to Short Gull Tide Gauge]</p>

### SUMMARY

River Wall/Armour	Saltings	High Tide Debris Line
<p>The top of the wall showed greater wear, with the mud spread more widely, deeper puddles and more numerous tears in the webbing. It was dry when the walk took place. When wet, sections are unwalkable.</p> <p>Clearly, the continuing pressure of footfall in the absence of remedial work is increasing the damage to, and in places reducing the height of the wall year on year.</p> <p>In the case of both the wall and the saltings, photos do not do justice to the extent of the change over recent years; particularly the undulations in the level of the wall.</p>	<p>Erosion continues. The photos show ways in which the saltings are being depleted in chunks.</p>	<p>No change</p>

### Area Surveyed:



## OVERVIEW & PHOTOS

As described above.



Photo 1

Showing the way in which the footpath is encroaching on the side of the wall



Photo 2  
State of the armour



Photo 3  
Showing a piece of saltmarsh detaching



Photo 4  
[and following photos] shows the condition of the webbing and possible trip hazards



Photo 5



Photo 6



Photo 7  
Saltings Erosion