

# THE ALDE & ORE ASSOCIATION

Registered Charity No. 1154583



## ALDE AND ORE ESTUARY ASSESSORS REPORT

<b>NAME[S]:</b> Frances Barnwell Christopher Gill	<b>DATE OF INSPECTION:</b>  03.04.22
<b>4.2</b>	<b>AREA OF ASSESSMENT:</b>  <b>Orford Sailing Club to Short Gull Tide Gauge</b>

### SUMMARY

<b>River Wall/Armour</b>	<b>Saltings</b>	<b>High Tide Debris Line</b>
<p>As in earlier reports, the top surface of the wall shows further deterioration. This is particularly evident in the section covered by webbing. The webbing is disintegrating with numerous breaks that expose obvious trip hazards to those using the path.</p> <p>The top is visibly undulating as puddled areas wash away or spread.</p>	<p>As in previous years, the photos show ways in which the saltings are being depleted in chunks. There is no compensatory accretion.</p>	<p>No change</p>

### Area Surveyed:

Orford Sailing Club Club House to Short Gull Tide Gauge

As described above





















