

THE ALDE & ORE ASSOCIATION

Registered Charity No. 1154583




ALDE AND ORE ESTUARY ASSESSORS REPORT

NAMES: A McDonald J Maxim	DATE OF INSPECTION: 02/04/2022
FLOOD CELL: FC4.1	AREA OF ASSESSMENT: Gedgrave & Sudbourne Marshes

SUMMARY

River Wall/Armour	Saltings	High Tide Debris Line
All in good order	Considerable wear and undercutting above Butley Ferry and now above Boyton Dock and along the Gull. Opening to the tidal channel is widening, and the inner channel has extended upstream and is wider than in previous years. Standing water (see photo #17) along Gull saltings presumed to be from previous day's very high tide, but not noticed previously.	Fairly clear compared with previous years

River Bank Surveyed:



OVERVIEW & PHOTOS

Inner walls and pathway:



By Pinneys
TM 397 486



Worn Path
TM 397 474

Saltings:



Inner Channel above Boyton Dock
TM 394 482



Widening Channel
TM 395 474



Tidal Water in Saltings
TM 403 473

Outer Walls:



Armour Upstream of Pumping Station
TM 411 475