

THE ALDE & ORE ASSOCIATION

Registered Charity No. 1154583



ALDE AND ORE ESTUARY ASSESSORS REPORT

NAME: Roger Baxter Jonathan Evans	DATE OF INSPECTION: April 2026
FLOOD CELL: FC2	AREA OF ASSESSMENT: Butley Mills

SUMMARY

River Wall/Armour	Saltings	High tide Debris Line
Substantial	Deep and well vegetated	Not Visible

River Bank surveyed:



Upstream part of River Butley with wide, flat saltings populated by dense reed beds. River Wall is high and wide with a mechanically controllable sluice to allow drainage (under the road) from the mill pond. Grass is thick and short with a footpath on top. The steps from the road to the sluice controls/wall top have recently been replaced.



