

THE ALDE & ORE ASSOCIATION

Registered Charity No. 1064789




ALDE AND ORE ESTUARY ASSESSORS REPORT

NAME: Jane Salter Roger Baxter	DATE OF INSPECTION: 8th April 2017
LOCATION: Flood Cell 2	
AREA OF ASSESSMENT: Butley Mill	March Equinox

SUMMARY

River Wall/Armour	Saltings	High Tide Debris Line
Wall in good condition [See Photograph 1]	Extensive reed beds	None evident

River bank surveyed



OVERVIEW

- Last year there was a problem due to a lack of grass cutting. This has now been resolved by the Parish Council and Environment Agency and there is currently a regular maintenance programme in place for the wall.
- Horses had been using the top of wall in 2016. The Parish Council intend putting up signs at each end prohibiting horses (although, so far, there is no evidence of usage this year).
- Sluices clear and working efficiently (See Photograph 2)



Photograph 1



Photograph 2