

THE ALDE & ORE ASSOCIATION

Registered Charity No. 1154583




ALDE AND ORE ESTUARY ASSESSORS REPORT

NAME:	Simon Reid Maggie Scorer	DATE OF INSPECTION:	5th April 2017
LOCATION:	Flood Cell 4-3		
AREA OF ASSESSMENT:	Orford to Pump House Sudbourne Marshes		March Equinox

SUMMARY

River Wall/Armour	Saltings	High Tide Debris Line
Good front and back slopes with top of wall in good state, helped by sheep grazing (see Photograph 1)	Variable (see Photograph 2)	Generally well below top of wall

River bank surveyed:



OVERVIEW

- River wall remains in good condition. Vegetation thick, assisted by sheep grazing.
- Saltmarsh variable in width.

Funding and design for restitution being arranged by the Saltmarsh Group and Environment Agency. Up to 1000m are vulnerable. The area of distinct erosion is a priority to avoid wave action on river wall.



Photograph 1
(N 52 6.755 E 001 34.024)



Photograph 2
(N 52 6.755 E 001 34.024)