

THE ALDE & ORE ASSOCIATION


Registered Charity No. 1064789



ALDE AND ORE ESTUARY ASSESSORS REPORT

NAME: Roger Baxter Alison Andrews John Grayburn	DATE OF INSPECTION: April 2016
LOCATION: Flood Cell 9	March Equinox
AREA OF ASSESSMENT: Brick Dock to Hazlewood Marshes Breach	

River wall inspected:



Brick Dock Area

- Beach and saltings remain in good condition, although some washout of vegetation is evident in places at low tide.
- There is some overtopping debris on the concrete retaining wall at the bottom of some houses, although there has been no garden flooding. This remains from 2015.
- The river wall to the west has two areas of revetment damage.
- Further erosion is evident to the west of Roundhill under concrete revetment.
- Bramble and shrub growth needs removing on back slope at foot of Roundhill and adjacent property.
- On the marsh, the main breach is impassable on foot, as this breach (one of several going upstream) has been widened to allow ebb tides to drain the marshes. (As reported in 2015).

Erosion to Revetments (2 areas)



Debris below wall



Erosion to vegetation on beach



Erosion to wall at Roundhill

