

THE ALDE & ORE ASSOCIATION

Registered Charity No. 1154583



ALDE AND ORE ESTUARY ASSESSORS REPORT

NAME: Roger Baxter	DATE OF INSPECTION: 13 June 2018
LOCATION: Flood Cell 2	AREA OF ASSESSMENT: Butley Mills

SUMMARY

River Wall/Armour	Saltings	High Tide Debris Line
Good condition but foliage needs cutting. No sign of horse traffic as has been evident in the past.	Deep marsh with reed beds	None

River Bank Surveyed:



PHOTOS



