

THE ALDE & ORE ASSOCIATION

Registered Charity No. 1154583




ALDE AND ORE ESTUARY ASSESSORS REPORT

NAME: Simon Reid	DATE OF INSPECTION: 15 June 2018
LOCATION: Flood Cell 4.3	AREA OF ASSESSMENT: Pump House to Orford Quay

SUMMARY

River Wall/Armour	Saltings	High Tide Debris Line
Mostly good with well established grass.	Variable. Some areas shallow, others with lagooning. Attenuation to be installed soon.	Low – no problem.

River Bank Surveyed:



OVERVIEW & PHOTOS



Bushes on either side of the river wall (GR 444516)



Erosion foot wall (GR 438500)
No worse than last year



Slight hole/indentation on top of wall (GR 444510)