

THE ALDE & ORE ASSOCIATION

Registered Charity No. 1154583



ALDE AND ORE ESTUARY ASSESSORS REPORT

NAME[S]: Simon Reid Sue Ingham	DATE OF INSPECTION: 25 March 2020
FLOOD CELL: FC4.3	AREA OF ASSESSMENT: Orford Quay To Pump House

SUMMARY

River Wall/Armour	Saltings	High Tide Debris Line
[Same as 2019] Mostly good with well established grass. Fine back slopes	[Much same as 2019] Variable. Some areas shallow, others with lagooning.	[Same as 2019] Low – no problem.

Area Surveyed:



OVERVIEW & PHOTOS

Grid Ref: 454 533

Extensive bushes either side of river wall

Photo 1



Photo 2



Grid Ref 433 497

Alexander (?) spreading all along river wall from Orford

Photo 3



Grid Ref 433 498

Dip in river wall

Photo 4



Grid Ref 432 498
More Alexander (?)

Photo 5

