

THE ALDE & ORE ASSOCIATION

Registered Charity No. 1154583




ALDE AND ORE ESTUARY ASSESSORS REPORT

NAME[S]: Simon Reid Sue Ingham	DATE OF INSPECTION: 27 March 2020
FLOOD CELL: FC4.4	AREA OF ASSESSMENT: Pump House to Chapmans Creek

SUMMARY

River Wall/Armour	Saltings	High Tide Debris Line
Good Vegetation	Westrow Reach poor	Low, not a problem

Area Surveyed:



OVERVIEW & PHOTOS

Grid Ref: 453 550 to 458 553

River wall well covered in vegetation, except where horses have caused extensive compaction at above location.

Photo 1



Grid Ref: 459 553

Generally river wall in good shape on both front and back slopes – but netting has come away from stakes on the attenuation system at 459 553.

Photo 2



Grid Ref: 460 553

Whereas netting still in place at 460 553.

Photo 3



Would not expect this stretch of river wall to change dramatically in near future.