

THE ALDE & ORE ASSOCIATION

Registered Charity No. 1154583




ALDE AND ORE ESTUARY ASSESSORS REPORT

NAME: R Baxter	DATE OF INSPECTION: 24 April 2020
FLOOD CELL: FC9	AREA OF ASSESSMENT: Brick Dock to Hazlewood Marshes

SUMMARY

River Wall/Armour	Saltings	High Tide Debris Line
Thick grass with good slopes. Except as below	Erosion continues under vegetation on beach area – otherwise good.	No problems

Area Surveyed:



OVERVIEW & PHOTOS

River wall at the dock end is in good repair with good vegetation on saltings in places.

Vegetation root washout continues where there is a sandy base, but this does not appear to be a serious problem.



Photo 1

Saltings are deeper towards Round Hill and in good condition .



Photo 2

The revetment work is breaking up in places with some significant erosion at the water line.
Requires EA inspection sometime.

Should a breach occur in the future, the area to be flooded would be downstream of Hazlewood marsh and flood the lower half of the Round Hill meadow and adjoining areas of the golf course.



Photo 3



Photo 4



Photo 5

The back and front slope debris line are the same height as a result of the winter surge which flooded this area from the Hazlewood breach.



Photo 6