

THE ALDE & ORE ASSOCIATION

Registered Charity No. 1154583



ALDE AND ORE ESTUARY ASSESSORS REPORT

NAME: Dinah Welsh Nicholas Russell	DATE OF INSPECTION: 29 May 2026 Previous inspection: 24 April 2018
FLOOD CELL: FC3	AREA OF ASSESSMENT: Ferry Cottage to Chillesford Lodge

SUMMARY

River Wall/Armour	Saltings	High tide Debris Line
Good, no loose amour bricks noted.	Good	Low – 1.5 metres below wall top

River Bank surveyed:



OVERVIEW AND NOTES

All walls covered in vegetation with no visible cracking and no risk of erosion in the event of over-topping.

Note: part of this section is now on the King Charles III England Coastal Path.



Location: 52.08532 N / 1.49879 E



Location: 52.08584 N/ 1.49937E



Location: 52.08619N / 1.4986 E



Location: 52.09704 N / 1.49633 E



Location: 52.10078 N / 1.49407 E