

THE ALDE & ORE ASSOCIATION

Registered Charity No. 1154583




ALDE AND ORE ESTUARY ASSESSORS REPORT

NAME: Roger Baxter Jonathan Evans	DATE OF INSPECTION: 1 st July 2026
FLOOD CELL: FC7	AREA OF ASSESSMENT: Snape Bridge to Blackheath

SUMMARY

River Wall/Armour	Saltings	High tide Debris Line
Good Condition. Narrow Top. (well used but with vegetation. <i>Not yet struck</i>) Banks with good vegetation.	Mostly at the bottom of the Warren. Deep, flat. Reed Beds to the East between wall and tidal channel.	Low, little evidence.

River Bank surveyed:



OVERVIEW & PHOTOS



Cygnet and other craft moored at Snape Quay

Start of path off Snape Bridge showing IR counter



IR Counter also shows good growth of reeds



Sluice in good order

Narrow path with good vegetation on both sides of wall

