

THE ALDE & ORE ASSOCIATION

Registered Charity No. 1154583




ALDE AND ORE ESTUARY ASSESSORS REPORT

NAME: Roger Baxter Jonathan Evans	DATE OF INSPECTION: 1 st July 2026
FLOOD CELL: FC9	AREA OF ASSESSMENT: Brick Dock to Hazlewood Marshes Breach

SUMMARY

River Wall/Armour	Saltings	High tide Debris Line
Thick grass with good slopes to point of breakthrough. The breakthroughs are slowly growing but no new ones have appeared. Spits appear to be forming at the breakthroughs into the river.	Erosion continues under vegetation on beach area otherwise good. Saltings at low tide healthy with good quantity of worm casts.	High tide debris evident against concrete wall for 100m. The saltings at this point appear to be extending. No problems.

River Bank surveyed:



OVERVIEW & PHOTOS



Sea wall at path to dock well vegetated and good condition



View west at Brick Dock



Good vegetation on sea wall



High tide debris up to concrete wall



High tide debris to to concrete wall





Extensive worm casts